



Case History - Burn Over Diamond Mill

SUMMARY:

The target was a 2.550" matrix body diamond mill left down hole because of a parted weld with loose carbide on top from previous caribe shoe and mill runs. The XDS shoe burned over the loose junk and 2" of diamond-set matrix gage in 5 hours on motor/CT

